



SIDE IMPACT AIR BAG LOCATION! "Yellow Sheet" 10-08-2004

©North Memorial Medical Center/ABRA Auto Body & Glass 1-800-994-9780
with 2004 Detroit Auto Show updated by Dave Long

- All canister locations verified with OEM service manual diagram, OEM might change location due to needs.
- Canister locations are not labeled by OEM, Most all OEM label side and side curtain airbags
- All **but** Volvo 850, 960 & 70 Series, 1993 to 1995 Cherokee front bags and pre 1996 Jaguar front bags (aforementioned are **Mechanical**) bleed down electrically according to your **deactivation chart**.
- All have seat belt **pre-tensioners** in "B" pillar that fire up into B-pillar or into rocker panel and triggered mechanically or sensors independently located low in "B" pillar. Some models with pretensioners for rear seated occupants.
- **Pretensioners are on top of "B" pillar on Volvo, some autos on buckle side or low B-pillar**
- All are pre-set to deploy at **185°/270° to 350° Fahrenheit** in a vehicle/electrical fire - Use caution!
- A plugged in **Cell phone** or **theft alarm** or **accessories** will bleed power back into all electrical systems.
- The "HPS" and the "IC" and curtain/window airbags deploy with thorax or head-thorax (side) bags.
- **Batteries** are in the trunk/back seat in many newer vehicles, and Toyota Prius HEV.
- 1997 and newer GM full size Van and GM & Ford Pickups & Dodge Prowler have **magnesium** cross members in the dashboard. Use caution in vehicle fire! Magnesium burns on its own once ignited and water application increases the burn! 04 F-150 has magnesium radiator core support.
- Consider battery safety terminals (BST) (i.e. BMW 5 & 7 Series) an additional hazard in a vehicle fire!
- **Consider all vehicles that have frontal Dual Stage or Multi Stage Inflator airbags to be LIVE AGAIN even if deployed after a crash.**
- **Vehicles with EPG glass/laminated/dualpane side (Break Resistant) and backlite glass vs. tempered are available. Be prepared for another entry. May be in: Audi, BMW, Cadillac, Ford or Lincoln SUV, Mercedes, or Volvo or other safety & security glass or armored vehicle.**
- **Cars with Advanced Airbags passenger side airbag supression sensors right front seat: Children should always be buckled up in back! FMVSS208 Rule required in 2006. Occupant Classification System (OCS) or (PODS) Passenger Occupant Detection System : 03-04 Acura MDX SU, 04 BMW X3 SUV and 5 Series and 6 Series and Z4 Roadster, 03 GM/Chevrolet C-Truck /Suburban/Tahoe, 04 Malibu, 04 Chrysler Pacifica, 300C & Dodge Magnum, 05 Town & County Minivan, 04 F-150 Pickup, 04 Freestar/Monterey, 04 Mazda MPV, 05 Mazda Tribute, Mazda 3, Mazda 6 S[port Wagon 04 Mercury Mariner, 04 Durango, 05 Dodge Caravan, 05 Honda Odyssey, 04 Nissan Quest, 04 Taurus/Sable, ,04 Honda Accord & Oddesy van, 04-05 Kia Spectra, 04 Nissan Titan, Infiniti QX56 and Nissan Pathfinder Armada SUV, 04 Pontiac G6, 05 Subaru Legacy, 04 Toyota Highlander & Sienna, 04 VW Touraeg, 04 VW Convertible and most 04-05 models!**
- **IF SIDE & CURTAIN BAGS HAVE DEPLOYED IN ANY CRASH into seated person, 2000 or newer Advanced bags, OR ANY DEPLOYMENT (with severe-fatal bag injury), windshield pop out/failure, Equipment-Technician injury; CALL (202) 493-0400 (24HRS), complete and fax Special Crash Investigation (SCI) Form to NHTSA OR contact www.nhtsa.dot.gov keyword: Airbags, NCSA, SCI form**

Acura – "**3.5 RL**" model- Front SEAT mounted bags with SENSOR in door,

- Multiple R/F seat sensors cut power if child out of position, wt & position sensors

.Acura 3.2 TL ,.3.2 CL,.MDX SUV, . RSX {R/F seat sensor for side bag } outboard side of SEAT)

04 Acura TL - front side thorax seats, 1-2 row head curtain airbag=6. Canister in Low C-pillar. Curtain Rollover sensor detection

Acura TSX - front outboard seat thorax, head curtain = 6, canister low in C-pillar

04 MDX SUV- front side thorax seats =6. 1-2-3 row curtain airbag, Canister in roof rail above middle door and ? Low A pillar? Curtain Rollover sensor detection

Audi A8, A8L, S8 f/r, A6 - Outboard side of SEATS front and rear = 8 airbags

800-822-2834

TT Coupe – Outboard SEAT facial and chest

A4 - Outboard side of SEATS front and rear with single SENSOR module under front seat

04 Audi A4 Cabriolet Convertible - front side seat, pop up roll bars

2000-3 All models plus & S4, All Road Quattro, all but TT – f/r outboard SEATS &

Sideguard 1-2 row window airbag – **NOTE!** - Deploys down from roof, compressed gas cylinder low on C-pillar {Post crash; doors unlock, interior lights on, 4 way flashers on, auto shut off of fuel pump}

04 Audi A8 V12 - rear side seat, driver and passenger knee bags and above = 10 airbags!

Austin Martin Vanquish and DB9 - Front side seats

BMW 3, 5, 6, 7, Z3, & Z8 Series, X3 & X5 “SAV”- Front & Rear DOOR panel mounted side bags 800-831-1117 - Single SENSOR module between front seats.

NOTE! - “HPS” front bags deploy across the front door glass opening, and are anchored behind “B” pillar and at bottom of “A” pillar. It is tucked under the headliner and windshield post cover molding with inflator modules under dash in side kick panel below “A” pillar with nitrocellulose as the propellant.

3 Series Convertibles & M3 – Pop up roll bar / headrests

5 Series, M5, 7 Series-740i, 740iL, 750i, 750iL, 760 series- front rear side HPS, f/r side DOOR mounted = (10 or 12 airbags) 7 Series had driver and passenger knee airbag

- Rear HPS deploys down from roof and C-pillar, Only canister which is below C-pillar and bottom of window line includes 745/745Li/760 Series

745/745Li and coming 760Li with 2 knee airbags in front = 12 AIRBAGS!

645 Series C/CIC Convertible 3/04 pop up roll bars, ROPS

Cadillac Catera, Concours & All DeVille DHS, DTS f/r -Front DOOR (newer have f/r seat) panel mounted side bags -SENSOR in door – fuse in trunk

2003 Cadillac CTS – 6 airbags, 1-2 row curtain and front outboard SEAT mounted— CAUTION! canister in roof rail between A and B pillars!

Seville/XLR Roadster -Outboard side of front & rear DOOR,

(.Cadillac Escalade, .Escalade EXT/Equinox SUV) - Outboard SEAT mounted airbags

Cadillac SRX - front side seat, 1-2 row head curtain, canister top of C pillar in roof rail?

Chevy Venture, .GM Truck, GMC Yukon, .Yukon XL, .Chevy Suburban, .Tahoe, .Cavalier, Avalanche, .GMC Envoy 04, Cavalier, SSR, Trailblazer and EXT)

Outboard side bag of front SEATS

Chevy Equinox SUV- 1-2 row curtain airbag, canister in roof rail between C & D pillars

04 Chevy Malibu & Maxx- 1 & 2 row head curtain, canister at top of C-Pillar. 4 airbags.

04 Chevy Colorado Pickup - head curtain airbag=4. Canister in roof rail above doors bet A & B

05 Chevy Cobalt - head curtain airbag, 1-2 row, Canister Unknown _____

05 Chevy Uplander Minivan- Canister Unknown _____

Bentley Arnage T24 and RL - front side seat, 1-2 row curtain airbag. Canister unknown_____.

Bentley Continental - 1-2 row curtain

Buick Century, Chevy Impala, Chevy Monte Carlo, Buick Regal = 3 airbags

Drivers SEAT only . Check passenger seat.

Buick Rendezvous SUV/ Rainier - seat head thorax airbag

Pontiac Bonneville, Buick LeSabre & Park Avenue, = 4 airbags

R & L front SEAT

Chevrolet Prizm -Front DOOR panel mounted side bag-SENSOR in lower rear corner of front door

Chrysler Crossfire 04 - NOTE! D/C SLK car! Door mounted side airbags!

05Chrysler 300C, LX-driver knee blocker airbag, 1-2 row curtain, inflator in low C-pillar =5

05 Chrysler Town & Country Minivan - driver knee blocker airbag, 1-2-3 row curtain airbag, inflator in roof rail just behind the C-pillar

Chrysler Sebring/Dodge Stratus-Full Curtain bag, hybrid canister in lower ½ of C-pillar

Chrysler Pacifica – drivers side knee bag (NOT LABELED), 1-2-3 row head curtain = 5. Canister in center roof rail between B-C pillars above slider door

Dodge 200I+ Caravan, Chrysler T & C Van, PT Cruiser and PT Convertible, Neon, LHS, Stratus, Concord, Intrepid, SRT-4 – outboard front SEATS

Dodge Ram 1500-2500-3500 Pickup – head curtain airbag, canister horizontal in roof rail inbetween B and C-pillars

03 Dodge Durango – 1-2 row curtain airbag, Hybrid canister in roof rail above ¼ glass bet. C & D

04 Dodge Durango - 1-2-3 row curtain airbag, hybrid canister in roof rail near top of B-Pillar forward toward A-pillar

05 Dodge Caravans - driver knee blocker airbag (NOT LABELED), 1-2-3 row curtain airbag, inflator in roof rail just behind the C-pillar

05 Dodge Magnum- 1-2 row curtain airbag. Canister in C-pillar.

Ford Explorer, Escape, Focus, Taurus, Windstar, 2002-4 Thunderbird ,04 Crown

Victoria sedan and convertible-Outboard side of front SEATS

(.Escape, .Expedition, .Excursion, .F-150 Super Crew, .Harley Davidson F-150 Super Crew – Outboard side of front seats

(Window bag 2002-4+ Explorer/Mountaineer/Sport Trac/03+ Expedition/Navigator/03+ Excursion, Aviator, 05 Hybrid Escape) “Safety Canopy System” curtain 1-2 row airbag deploys in side impact & roll over, Canister in roof rail above ¼ glass between C and D Pillars. Look 4 seat bag.

04 Ford Freestar/Mercury Monterey Van - front side seat, and 1-2-3 row head curtain airbag Safety Canopy System. = 4 bags. 2 Canisters in roof rail above mid door and above 1/4 glass!

05 Ford Five Hundred - OCS, front side seat thorax, 1-2 row *Curtain*. Canister in low C-pillar. Roll over sensing-Safety Canopy System

05 Ford Freestyle- OCS, front side seat thorax, 1-2-3 row curtain. NOTE TWO canisters! in roof rail one above C-Pillar, second canister in roof rail between C and D pillar. Roll over sensing-SCS

Honda Accord- R/F SEAT has dual threshold inflator. Front SEAT bag LX V6, EX V4, V4 leather **(.Honda XG3, Civic, Civic Hybrid, CR-V, Element)** (OPDS frontal airbag system)

04 Honda Accord - 11/01 front seat torso and 1-2 row head curtain, Canister in low C-Pillar.

05 Honda Odyssey - AAB, front side seat, 3 row head curtain, Canister in roof rail behind C-pillar

Hyundai Sonata – Front SEAT mounted. SENSOR in outboard side of seat **(.XG 350 Wagon, .Elantra, .Tiburon, .Accent, .Santa Fe)** {35 lb. passenger side bag protection in RF seat on most models}

05 Hyundai Tuscon SUV- front side seat thorax, 1-2 row head curtain, Canister in D-Pillar!

Infiniti Q45, QX4, I-30, I-35, J30 & G20 - Outboard side of front SEAT

Infiniti G35 Coupe 1-2 row head curtain airbag, inflator canister low in C-pillar

Infinity Q45 2002+ with side head 1-2 row curtain, argon canister low in C-pillar

Infiniti FX35 Crossover, FX 45 front outboard seat thorax, head 1-2 row curtain =6, inflation canister in roof horizontal at/across backglass

Infiniti M45- front outboard seat thorax, 1-2 row head curtain =6, canister low in C-pillar

Isuzu Ascender SUV- outboard side front seats thorax bag

.Jeep Wrangler Sahara, .Grand Cherokee – Outboard side of SEAT

.Jeep Liberty & Grand Cherokee–1-2 row curtain bag, hybrid inflator above ¼ glass in roof rail in-between C and D pillar.

Jaquar “S” Type & XJ Series (.Jaquar Vandan Plas, & .X400) – Outboard side of front SEATS (Pre- 1996 driver bag is *mechanical* - CAUTION!)

& **.XKR type** – SENSOR in “B” pillar above belt retractor

& .XJR, .XJ8 (Single point sensor below radio)

02 Jaguar "X" Type, 03-4 S Type, XJR, XJ8, Vanden Plas – front side thorax seat, 1-2 row curtain airbag, argon gas low in "C" pillar =6

XKS and XK – Ultrasonic sensor for passenger side airbag and children

Kia Sportage - Knee airbag/bolster - deploys below dash panel on driver side = 3 bags. END in 01

Kia Sorrento SUV 1-2 row head curtain airbags =4, canister in roof rail between C & D pillar

Kia Amanti 04- side thorax front and rear seats and 1-2 row head curtain, CAUTION! canister in top of A pillar. = 8 AIRBAGS

Kia Optima – SEAT mounted torso/head side bag

04-05 Kia Spectra - front side seat, 1-2 row curtain. Canister unknown na4/07_____.

Ranger Rover-Land Rover 4.0 SE, & 4.6 HSE – Front side SEAT bags only

03 Range Rover –8 Airbags

front side in doors- door mounted front only

front head airbags- tubular shaped airbags in A pillar, gas canister at base of A-pillar

rear head airbags = small curtain style airbag out of roof, gas canister in roof toward center

Lexus LS400, GS & SC 300, 400, 430 & ES 300, IS 300&SC Outboard side of front SEATS

Lexus LS 430 - outboard side SEAT f/r, 1-2 row curtain bag, argon gas canister in low C-pillar.

04 Lexus LS and 05 GS 430 also will have driver and passenger knee airbag

Lexus GS 300, GS 430, IS 300 & SportCross - 1st row curtain, canister at bottom of A pillar!

03 GX 470 SUV/LX470 – front outboard seat thorax and 1-2 row head curtain =6, Canister in roof rail above ¼ glass between C and D pillars

ES 300 – ½ curtain, canister at bottom of rear C pillar along side of rear seat per CA technician!

Lexus RX 300 SUV – Outboard seat mounted

Lexus RX 330 SUV - Outboard front seat thorax, drivers knee bag, 1-2-3 row head curtains = 7, Canister in center roof rail between B and C pillars

Lexus SC 430 – Outboard side of seat, (retractable hardtop edition) 3/01

Mercury Mountaineer, Lincoln Continental, LS, Town Car & Cougar-Outboard side of front seat

Lincoln .Navigator. Aviator - Safety Canopy System - SEE FORD 2002 EXPLORER NOTE!

Lincoln .Blackwood Pickup 05/07/01 – Outboard side of SEAT

04 Lincoln LS- side front seats and curtain airbag, canister in low C-Pillar

Mazdaerati Quattroporte 9/04 - front side seat, rear side seat optional, 1-2 row curtain, canister unknown_____.

Mazdaerati Spider Coupe/Cambiocorsa- front side door

Mazda 626, MPV ES, Protégé .Tribute, .Millenia – Outboard side of front SEATS

Mazda 3 - front outboard side seats, 1-2 row curtain, inflator in low C-pillar = 6

Mazda 3 Sport Wagon- front outboard side seats, 1-2 row curtain, inflator in roof cross member above 5 door tailgate hatch = 6

Mazda 6 - front side thorax seat, 1-2 row curtain, Canister low in C-pillar. = 6 airbags

Mazda RX-8 - front seat thorax and head curtain. Canister in low C-Pillar. = 6 airbags.

Mini Cooper (by BMW) front thorax seat-mounted, front to rear AHPS2 advanced head protection "tubular curtain", nitrocellulose canister at bottom of C-pillar near seat line = 6 airbags

Mercedes Benz CL, E, S, SL, SLR, SLK 320 & M Class (ML320, ML430, ML55 AMG)

800-367-6372 -DOOR panel mounted bags. All newer 4 doors f/r standard + Window bag = 8

-Single SENSOR module in dash behind radio (Frontal passenger bags will not deploy if seat is unoccupied)

"C" & CLK 320 (.430) Cabriolet & Convertibles, CLK & SL – Pop up roll bar / headrests

-DOOR mounted

SENSOR located in each and activates both

"M" Class Sport Utility

(Foot bags now in Europe in some Mercedes models)

- DOOR panel mounted side bag -Single SENSOR module in dash behind radio
- Window bag 02 –1-2 row curtain, canister above ¼ glass in roof rail

NOTE! The “Window bag” is in the “E” and “S” class in 1998+ and now CL 500, CL, CLK & 2001+ & Newer
The bag deploys down from the roof between “A” and “C” pillars. All 1-2 row.
(Approximately 6’x14”x2”) – Inflater module in “C” pillar contains compressed argon gas at
3000>10,000PSI.

Sensors are in the “B” pillar above belt retractor and “C” pillar low on jamb of dogleg.

C320 Wagon and E Wagon - Window bag canister in roof rail above C pillar and ¼ glass

Mercedes SL-500/SL Class – head thorax side doors and drivers knee airbag = 5 airbags
(Some Mercedes have Baby Smart Infant Seats with infrared sensor for passenger airbag)

2003-4 Mercedes E Class! - thorax side bags front Seats and rear Doors BUT! head curtain
inflation canister in LOW to MIDDLE OF A-PILLAR! =8 bags. Rollover deployment for side bags.

Mercedes Benz SLR McLaren- front doors

Mercury Sable/Cougar/Grand Marquis-outboard side of front seat

04 Ford Freestar/Mercury Monterey Van - front side seat, and 1-2-3 row head curtain airbag
Safety Canopy System. = 6 bags.

**Mitsubishi Galant, Eclipse, .Montero, Endeavor, Outlander.Spyder, Lancer and
Lancer Wagon** - torso front side of SEATS,

Nissan Altima, Maxima (.Sentra/.350Z Convertible/ Z Roadster - Outboard side of front
SEATS)

02-03+ Pathfinder- outboard thorax side front seat and 1-2 row head curtain airbag,
canister in rear roof rail above tailgate at the rooftop!

02+ Altima – thorax side seat-mounted, 1-2 row curtain airbag. Hybrid Canister low in C-pillar

04 Nissan Maxima front side seat thorax, head curtain =6, canister low in C-pillar

Nissan 350Z - front side thorax, 1st row head curtain =6, canister in roof horizontal @ back glass

Nissan Murano- front side thorax, 1-2 row head curtain =6,canister horizontally roof @ back glass!

***Nissan Quest Minivan**- front side thorax seat, 1 row and 2-3 row head curtains=8, Canisters low
A pillar and between C & D pillar in roof rail above slider door

.Nissan Pathfinder- 02-03 1-2 row Curtain airbag, canister in roof rail between C and D pillar

04 Nissan Pathfinder Armada and Infinity QX56 SUV - front side seat & 1-2 row and 3
row curtain =8. Canisters in low A pillar and roof rail above C pillar toward D pillar.

04 Nissan Titan Pickup - front side seat & head curtain =6. Canister at base of A-pillar.

04 Nissan Xterra - , curtain airbag. Canister in roof rail probably? between C & D Pillars

Oldsmobile Aurora, & Intrigue 2001+, 2001-2+ Bravada, Silhouette – front side seat

PIERCE OSHKOSH Series 8 FIRE TRUCK - 10" tubular head airbag X 3 feet (like BMW HPS),
side roll over deployment only at 60 degrees, Argon inflator high on B-pillar

Pontiac Sunfire, Vibe, Transport, Bonneville, Montana, Aztek – front side seats

04 Pontiac Grand Prix GT2/GTP- 1-2 row curtain airbag, canister at top of C-pillar =4.

Pontiac G6 - front side seat, 1-2 row curtain, Canister unknown_____.

Porsche 911's, 996 & Boxter - Front DOOR panel mounted. **Carrera** – Pop up roll bar +side
800-545-8039 - 911 Single SENSOR module in console. 30 L side airbag of Argon gas

Boxter's sensor is in rocker panel

(Porsche Child Deactivation RF Infant seat available from Porsche Dealer)

911GT3 911 Turbo and 911 Cabriolet- adj. roll bar, pop up roll bar (Supplemental Safety Bars)

Porsche Cayenne SUV- front side seat thorax, 1-2 row head curtain, and canister in D-pillar. =6.

Saab 9-3, 9-5 - Outboard SEAT mounted with air pressure sensor in door (**.Viggen, .Aero**)

03 Saab 9-3 front side thorax, 1-2 row head curtain =6, canister in roof rail forward from C-pillar

Saab 9-2X - front side seat, no curtain

04 Saab 9-3 Convertible - front side seat, pop up roll bars

Subaru Legacy –Outboard SEAT mounted bags -SENSOR in “B” pillar above retractor

05 Legacy/Outback Sedans- front side seat, 1-2 row curtain, Canister low C-pillar

05 Outback Wagon/Legacy Wagon - front side seat, 1-2 row curtain, Canister roof rail between C& D Pillars

(.Forrester, .Outback Limited, .STX concept pickup, 2001 .WRX Imprenza Sedan & Wagon 3/01) (Baja Truck coming in 9/02)- Front side seat mounted airbags

Saturn – (2001 S & L-Series sedan & wagon & VUE head Curtain bags, Canister location varies:

-L Series Sedan 1-2 row curtain, canister low in C-pillar

-L Series Wagon & VUE 1-2 row curtain, canister in top roof rail above ¼ glass

-S Series Sedan front ½ curtain only, canisters under instrument panel cover on top of column & above passenger bag, gas tubes run along top of L and R dash and up thru A-pillars

(All canisters are hybrid inflator of argon gas and nitrous oxide)

03 Saturn ION- 1-2 row head curtain airbag =4, canister low in C-pillar

Scion xA - front side seat, curtain airbag. Caution canister in roof rail above B-pillar

Suzuki - NO side airbags

Toyota Avalon, Camry, Celica, Corolla, Echo MR Spyder, Prius, Solara, & Sienna

.Highlander SUV, 03+Matrix -Outboard side of front SEAT

2001+Sequoia SUV -1-2 row curtain airbag, CAUTION! canister located low on bottom of C-pillar.

- hybrid inflator of Argon gas in C-pillar (unlike most SUV’s and wagons in roof rail)

02-03+ Camry, - 1-2 row curtain bag, canister low in C-pillar = 6 bags-Drivers airbag is three stage with 2 ignitors

04 Camry Solara- front side seat, 1-2 row curtain, Caution! Canister in roof rail between B and C pillar

05 Matrix/RAV- front side seat, 1-2 row head curtain Canister above B-pillar in roof rail

05 RAV- front side seat, 1-2 row curtain. Canister between B-pillar & C-pillar in roof rail

04 RAV 4/04 Highlander - front side seat, 1-2 row curtain, Caution! canister in roof rail between above B and in-between C pillar

03-04 Land Cruiser/03/04 4-Runner- front side seat, 1-2 row curtain airbag, canister in roof rail between C and D pillar

04 Sienna Minivan - front side seat thorax, 1-2-3 row head curtain, NOTE 2 CANISTERS! Front low A pillar and Rear D- pillar.

05 Tundra Limited Pickup- Front side seat, Head curtain. Canister in roof rail forward from C-pillar.

04 Prius Hybrid - front seat and 1-2 row curtain, canister in roof rail above B-Pillar to rear

05 Toyota Scion tC Sedan- drivers side knee airbag, front side seat thorax1-2 row curtain, Canister in roof rail above -pillar

(RCSA- Roll-Sensing Curtain Airbags: 05 4 Runner/Sequoia/Highlander have off switch for extreme off road driving for curtain airbags on left side of dash)

VW Beetle, Cabrio, Golf, GTI, Jetta, Jetta Wagon & Passat, Passat Wagon - Outboard side of SEAT Single SENSOR module under front seat)

- **.2001-2+ Passat GLS and Passat Wagon, Jetta & Jetta Wagon (>5/01), Golf**

- Side Curtain Protection, Hybrid inflation canister of argon gas in C-pillar in Sedans

- Canister in roof rail in all Wagon models between C & D-pillars. Note!: Golf & GTI canister at top of rear D-pillar!

VW Touareg SUV- front side seat thorax, 1-2 row head curtain, canister in D-pillar

VW Phaeton- 11/03, front seats, 1-2 row curtain airbag, canister low C-pillar.

Volvo 850, 960, C70, S70, V70 (Mechanical operation!). See Volvo SIPS OEM deactivation!

Volvo 40,60,70,V70, 80 & Cross Country (s+IC) (Electrical operation)

800-458-1552 -Outboard side of SEAT -Frontal passenger bags will not deploy if seat is unoccupied
C70 Series convertible also has Pop up Boron steel roll bar "ROPS" / headrests -SENSOR is located in each but activates both.

NOTE! The "IC" or Inflatable Curtain 1-2 row bag is in the "S" 90 model in 1998 and now 80 series + V70 2001 + Cross Country Wagon, and all newer 2001+ Volvos except convertibles = 6 airbags
The bag deploys down from the roof between the "A" and "C" pillars.
(Approximately 6"x14"x2") – Inflator module in "C" pillar contains compressed argon gas at 3000>10,000 PSI in sedans.

V70 & CC wagon - Inflator module canister located in roof rail & above ¼ glass.

XC 90- 5 Seater: front seat side SIPS, 1-2 row head curtain airbags =6, 1 canister in middle roof rail between C and D

XC 90-7 Seater -NOTE 2 CANISTERS! -front side SIPS, 1-2 row head curtain, canister location SAA, and 3rd row separate head curtain airbag, canister in D-pillar= 8 airbags

VOLVO XC90 & V70 Wagon & V50 Wagon note!; NO SIDE CURTAIN AIRBAG LABELING ON interior trim! General airbag labeling on the C-pillar on the Left side.

Volvo V50 Wagon - front side seats, 1-2 row curtain, Canister Unknown 8/27/04 _____.

© North Memorial Medical Center/ABRA Auto Body & Glass
The advanced intensive ALERT Airbag Safety Classes
Dave Long's 14 other Presentations Call
CALL 1-800-994-9780 x5452 dave.long@northmemorial.com
Detroit Auto Show New Vehicles for 04-05 Coming, Canister and
Airbags Unknown To Be Announced by OEM

Bentley Arnage
Chevy Cobalt
Chevy Uplander

Buick Terrazza van
Ferrari 612
Honda Hybrid Accord V6
Hyundai Mojave SUV
Mercury Maurader
Maybach 62
Lexus RX 400h Hybrid SUV
Honda Accord Hybrid
Rolls Royce Phantom
Pontiac G6
05 Toyota Corolla
Toyota Highlander Hybrid/Le
Scion 05 TC Sports Coup
Saturn Relay FUV
New Volvo S40 and V50 Wagon
New Volvo Convertible

Head Curtain
Head curtain side airbags, Nov.-Dec 04
Replaces Venture van, expect 5 star front and side, side
airbags and PODS for right front seat
Front side seat

Curtain, December 04
Unknown

Head Curtain
Unknown, January 05 or later Spring
Unknown, December 04 or later Spring
Head Curtain & drivers knee airbag
Head curtain, Canister unknown, Sept 04
Front side seat and side curtain=6
Unknown December 05 or later Spring
Curtain
unknown, fall 04
Curtain, canisters unknown
Door mounted inflatable curtain - DMIC in 2005